






nagarnela Lauruguama M the heoguen ! duot Terre del goto Farima sassuma amaruna a somethic I Amangequa. gachiban. Hipingom micana m PERET - Kingen nothing 8 1211110 All Jingen Mongo & Takorato & Farima Sumar Gongan M MINO PRO ATHACHSA ixe A. XICO.PR. xanachie tani (20 % Moguiza Vesconno vingin chienstem Jucain de the Bando. R. Remover from Hogara de Chicongo of Pehicagem 1 7abosingah tochinothu To The hiongo to wooder orri. R. Vome construm minora Angafu acani arie Anima MINO.B 20000 Zumocum nagahagno anagasache vando Tacacuque, Burnage All cunoquino MEAGO TACASKANE cangosina Azuquiama Nangafama Muix Guita an Mehi PROVAHATO Zasiame MEACO achenistche Telegeengites Canga NABYMANGA ammitu Tossa Beisteto: anaccafama Jamono roe suson / isole de los cutama rangaiaba Milail Tonormine nabasach Tamate. Tatalengin firmido isola anga








23 Anna Lane, Ladera Ranch, CA, USA







Q Search Tower by address

ID:1891

Secondary ID:-

Properties *

Orders *

Ω Jake Stutzman ▼

EDIT PROFILE

PRIORITY

High - April 25, 2019

PRIGRITY

MEASURE

000



Wear



Our evaluation of the property yields a set of problems that are considered high priority. Address problems as soon as possible.

PROBLEMS TO ADDRESS - HIGH PRIORITY:

FOOTPRINT

Identified







Roof Score Imagery: 04/25/19 12 out of 100 ● 0-25 ● 25×50 ● 50-75 ● 75-100

Hide Timeline

2019

April 25

INTERACTIVE IMAGERY ^

OVERHEAD SATELLITE

STATIC IMAGERY

2018

November 10

Aerial + Oblique

May 4

2017

DOTE


December 2 Aerial - Oblique

May 27 Acrial

January 8



Assigned To:- EDIT



Property Profile


223 AUBURN AVENUE, USA

BY PERIL ATTRIBUTES: Wildfire	Distance to Vegetation	0 ft.			
	Roof Covering	Shingle			
	Roof Tree Coverage	Yes			
PROPERTY CHARACTERISTICS	Roof Condition	Good			
VEGETATION COVER	Zone 1 - 10 ft: 15%				
	Zone 2 - 30 ft: 70%				
	Zone 3 - 100ft: 80%				


U.S. FOREST SERVICE WILDFIRE HAZARD POTENTIAL: MODERATE
































	Distance to Hydrant	Average of DAMAGE				
	< 250 Feet		1.79			
	> 250 feet AND <= 500 feet		1.81			
Action of the second	> 500 feet AND <= 1,000 feet		1.86			
	> 1,000 feet AND < =1,500 feet		2.14	<mark>19.6%</mark>		34-45
	Not yet covered in HydrantHub		2.25	<mark>25.8%</mark>		
	Fire Station Type	Average of DAMAGE			H	
	Full Time		1.82		THE STATE OF THE S	
AND THE RESERVE OF THE PARTY OF	Blended		2.23	<mark>22.5%</mark>		TO B
	Volunteer		2.60	<mark>42.9%</mark>	_	
	Grand Total		2.06			
		- 100 Care				
THE PARTY OF THE P	MANAGED AND ASSESSED ASSESSED.					1
					THE .	with the same
-/ 300						

	Distance to Hydrant	Average of DAMAGE		
	< 250 Feet		1.79	
	> 250 feet AND <= 500 feet		1.81	
Apple To Street on Local Con-	> 500 feet AND <= 1,000 feet		1.86	
	> 1,000 feet AND < =1,500 feet		2.14	<mark>19.6%</mark>
	Not yet covered in HydrantHub		2.25	<mark>25.8%</mark>
	Fire Station Type	Average of DAMAGE		
	Full Time		1.82	
AT IN THE SECOND	Blended		2.23	22.5%
	Volunteer		2.60	42.9%
	Grand Total		2.06	
3	Stations w/in 5 Mi	Average of DAMAGE		
	1-5 Stations		2.43	<mark>34.9%</mark>
	6-12 Stations		1.85	
	13-20 Stations		1.73	
A THE PARTY OF THE	21+ Stations		1.80	
THE PARTY NAMED IN	None		3.02	
1-300	Grand Total		2.06	


































GET /risks_and_enhanced_property

Example usage:


curl -H "Authorization: Token token=MzehsFAjJCzec2Vxyehy" "https://api.hazardhub.com/v1/risks_and_enhanced_property?lat=26.653622&lng=-80.0367709" -v

curl -H "Authorization: Token token=MzehsFAjJCzec2Vxyehy" "https://api.hazardhub.com/v1/risks_and_enhanced_property?address=1820+South+Ocean+Boulevard&city=Palm+Beach&state=FL&zip=33480" -v

Parameters

Field	Туре	Description	Example
lat	Number	Latitude of the point	26.653622
Ing	Number	Longitude of the point	-80.0367709
address	string	Address string	1820 South Ocean Boulevard







t took 2.155651475 seconds to process the request

Dashboard

Users

Settings

Batch Processor

Batch Stats

Partners API usage

Single Address

API Docs

Instructions

Single address lookup tool

Address Lookup

Point on google maps

```
▼ {
    ▼ risks: {
        address: "2 Anna Ln, Cropwell, AL, 35054",
        ▼ wildfire: {
            score: "A",
            text: "None/Very Low"
        },
        ▼ wildfire_description: {
            value: "Med_Dens_Interface"
        },
```







The top of the P&C insurance funnel where data is gathered - is leaky









Damaging Winds – 10 Year Probability Hail - 10 Year Probability Tornado - 10 Year Probability Lightning - 10 Year Probability 10 Meter Elevation Data 1 Meter Elevation Data Mold Formation Risk Frozen Pipe & Ice Dam Risk 50 State Wildfire Risk Sinkhole Risk (14 states with known sinkhole points) Underground Storage Tank Locations Clandestine Drug Labs High Resolution Flood Models Sea Level Rise Repetitive Drought Index

HazardHub In Action

637 Hibiscus Glen, Escondido, CA 92025



HazardHub *In Action*637 Hibiscus Glen, Escondido, CA 92025 – the basics

Nearest Fire Station – 1.1 Miles

Fire Station Name – Escondido FD Station 4

Fire Station Staffing – Full Time

Fire Response Area – Escondido Fire Protection Zone

Number of Fire Stations in 5 miles - 9

Nearest Hydrant – Less than 250 Feet Number of Hydrants in 1000 Ft – 18

AAIS Fire Protection Class – P2

Property Elevation – 400.3 ft

Distance to Coast – 13.48 Miles

Geocoding Accuracy - Rooftop





HazardHub *In Action*637 Hibiscus Glen, Escondido, CA 92025 – the risks

Wildfire Risk Score – "D"- High Risk

- Nearest Wildfire Perimeter Inside 2007 Witch Fire Perimeter
- **Distance to Significant Wildfire Risk** 958 to "Very High" Risk Zone
- Wind Region Santa Ana Katabatic Wind Zone

Earthquake Risk Score – "C" – Moderate

- MMI 7
- Shake Very strong
- **Richter Scale -** 4.6 5.2

Flood Risk Score - "A"

- 6195 Feet from the nearest river (San Dieguito River)
- 2389 Feet from the nearest water (Lake Hodges)
- 1617.95 Feet from the nearest 100 yr Flood Plain
- 68 feet above the nearest 100 yr Flood Plain



HazardHub *In Action*

637 Hibiscus Glen, Escondido, CA 92025 – the property

Property Type – Condominium

Garage – Yes – 2 Cars

Bathrooms – 2

Bedrooms – 3 4 (updated via MLS)

Year Built – 1983

Sq Ft - 2163

Owner 1 – John Siegman

Owner 2 – Roxanne Siegman

Exterior Construction - Stucco

Exterior Parking - Driveway

Exterior Roof - Tile

Exterior Sewer - Sewer Connected

Exterior Style - Spanish/Mediterranean

Cooling – Y, Central Air

Fireplace - YES

Heating - Forced Air, Gas Natural


Levels - 02 Story

Association Dues - \$245,


Last Sale Price: \$605,000

Replacement Cost - \$485,000









4728 Constitution Ave. Baton Rouge, LA



Bob's Insurance Company

1313 Mockingbird Ln Mission Viejo, CA, 92691 +1 (949) 555 1212 www.bobsinsuranceshack.com

Property Info



4728 Constitution Ave, Baton Rouge, LA, 70808, USA


Geocoding Accuracy:	ADDRESS
Latitude:	30.42117
Longitude:	-91.13585
A Property Elevation:	35.43 feet
Distance to Coast	53.69 miles - 11.28 miles

Property Info - Store / Office Combo

Building Area	L P AN ILLINOIS LIM 0
Lot Size	43560
Number of Stories	0
Year Built	N/A
Underground Storage Tank within 500'	Yes
Number of Tanks within 500'	3

Tax Asessor Value		
Total Assessed Value	\$1,240,350	
Total Market Value	\$8,523,500	
Valuation Model Estimates		
Mkt Value - High	\$21,212,590	
Mkt Value - Low	\$6,883,555	







Bob's Insurance Company

1313 Mockingbird Ln Mission Viejo, CA, 92691 +1 (949) 555 1212

www.bobsinsuranceshack.com

Property Info



4728 Constitution Ave, Baton Rouge, LA, 70808, USA

Geocoding Accuracy:	ADDRESS
Latitude:	30.42117
Longitude:	-91.13585
Property Elevation:	35.43 feet
Distance to Coast	53.69 miles - 11.28 miles

Property Info - Store / Office Combo

Building Area	L P AN ILLINOIS LIM 0	
Lot Size	43560	
Number of Stories	0	
Year Built	N/A	
Underground Storage Tank within 500'	Yes	
Number of Tanks within 500'	3	

Tax Asessor Value			
Total Assessed Value	\$1,240,350		
Total Market Value	\$8,523,500		
Valuation Model Estimates			
Mkt Value - High	\$21,212,590		

Advanced



Mkt Value - Low

Page 1

Risk Assessment





Grade: F Very high risk 49 Percentage risk: 9.76358% Square miles: 95% chance of 62.486943 ground strikes in 1 year per square mile

VERY HIGH RISK: Lightning

Advanced

\$6,883,555

